



IMPORTANT SAFETY RECALL

April 2014

Dear GM Customer:

This notice is sent to you in accordance with the National Traffic and Motor Vehicle Safety Act.

General Motors has decided that one or more defects as described below which relate to motor vehicle safety may exist in all 2008-2010 model year (MY) Chevrolet Cobalt, 2008-2011 MY Chevrolet HHR, 2008-2010 MY Pontiac Solstice, 2008-2010 MY Pontiac G5, and 2008-2010 MY Saturn Sky vehicles. As a result, GM is conducting a recall. We apologize for this inconvenience. However, we are concerned about your safety and continued satisfaction with our products.

IMPORTANT

- This notice applies to your 2008-2010 MY Chevrolet Cobalt, 2008-2011 MY Chevrolet HHR, 2008-2010 MY Pontiac Solstice, 2008-2010 MY Pontiac G5, and 2008-2010 MY Saturn Sky, VIN _____.

Until the recall repairs have been performed, it is very important that you remove all items from your key ring, leaving only the vehicle key. The key fob (if applicable), should also be removed from your key ring. Also, when exiting your vehicle, always make sure your vehicle is in “Park”, or in the case of a manual transmission, put the transmission into reverse gear and set the parking brake.

- Parts are not presently available to remedy your vehicle. When parts become available, GM will send you another letter to notify you to schedule an appointment with your GM dealer.
- The recall will be performed for you at **no charge**.

Why is your vehicle being recalled?

GM records indicate a defective Ignition & Start Switch or a kit containing a defective Ignition & Start Switch may have been installed in some 2008-2010 MY Chevrolet Cobalt, 2008-2011 MY Chevrolet HHR, 2008-2010 MY Pontiac Solstice, 2008-2010 MY Pontiac G5, and 2008-2010 MY Saturn Sky vehicles.

If your vehicle has the defective Ignition & Start Switch, there is a risk, under certain conditions, that your ignition switch may move out of the “run” position, resulting in a partial loss of electrical power and turning

off the engine. This risk increases if your key ring is carrying added weight (such as more keys or the key fob) or your vehicle experiences rough road conditions or other jarring or impact related events. If the ignition switch is not in the run position, the air bags may not deploy if the vehicle is involved in a crash, increasing the risk of injury or fatality.

Some of these vehicles may also have a condition in which the ignition key may be removed when the ignition is not in the "Off" position. If the ignition key is removed when the ignition is not in the "Off" position, unintended vehicle motion may occur: (a) for an automatic transmission, if the transmission is not in "Park"; or (b) for a manual transmission, if the parking brake is not engaged and the transmission is not in reverse gear. This could result in a vehicle crash and occupant or pedestrian injuries.

Until the recall repairs have been performed, it is very important that you remove all items from your key ring, leaving only the vehicle key. The key fob (if applicable), should also be removed from your key ring. Also, when exiting your vehicle, always make sure your vehicle is in "Park", or in the case of a manual transmission, put the transmission into reverse gear and set the parking brake.

**What
will
we
do?**

Whether or not your ignition switch has been previously serviced, GM will replace the ignition switch on your vehicle. This measure is being taken in an abundance of caution, to make sure all defective ignition switches have been removed from all vehicles.

PARTS ARE NOT CURRENTLY AVAILABLE, but when parts are available, your GM dealer will replace the ignition switch on your vehicle whether it is the original switch or a replacement, and for vehicles that have not previously had an ignition cylinder replacement under warranty, dealers will replace the ignition cylinder. Dealers will also cut and if necessary re-learn two ignition keys for each vehicle. This service will be performed for you at **no charge**. Because of scheduling requirements, it is likely that your dealer will need your vehicle longer than the actual service correction time of approximately 90 minutes.

We are working as quickly as possible to obtain parts. We will notify you with at least a second letter as soon as parts are available so that you can schedule an appointment with your dealer to have your vehicle repaired.

If required, your GM dealer will provide you with some form of courtesy transportation at no charge while your vehicle is at the dealership for this repair.

**What should
you do?**

When GM notifies you that parts are available, you should contact your GM dealer to arrange a service appointment. **Until the recall repairs have been performed, it is very important that you**

remove all items from your key ring, leaving only the vehicle key. The key fob (if applicable), should also be removed from your key ring. Also, when exiting your vehicle, always make sure your vehicle is in “Park”, or in the case of a manual transmission, put the transmission into reverse gear and set the parking brake.

**Did you
already pay for
this repair?**

When GM notifies you that parts are available, GM will also provide instructions for you to request reimbursement if you paid for repairs for the recall condition previously.

**Do you have
questions?**

If you have questions or concerns that your dealer is unable to resolve, please contact the appropriate Customer Assistance Center at the number listed below.

Division	Number	Text Telephones (TTY)
Chevrolet	1-800-222-1020	1-800-833-2438
Pontiac	1-800-762-2737	1-800-833-7668
Saturn	1-800-553-6000	1-800-833-6000
Puerto Rico – English	1-800-496-9992	
Puerto Rico – Español	1-800-496-9993	
Virgin Islands	1-800-496-9994	

If after contacting your dealer and the Customer Assistance Center, you are still not satisfied we have done our best to remedy this condition without charge and within a reasonable time, you may wish to write the Administrator, National Highway Traffic Safety Administration, 1200 New Jersey Avenue, SE., Washington, DC 20590, or call the toll-free Vehicle Safety Hotline at 1.888.327.4236 (TTY 1.800.424.9153), or go to <http://www.safercar.gov>. The National Highway Traffic Safety Administration Campaign ID Numbers for these recalls are 14V047 and 14V171.

Federal regulation requires that any vehicle lessor receiving this recall notice must forward a copy of this notice to the lessee within ten days.

For additional information regarding this recall, please go to www.gmignitionupdate.com.

Jim Moloney
General Director,
Customer and Relationship Services

GM Recall Numbers: 14092 and 14113 or 14133